

Schindler machines' updating.W53.45.1/2


REFERENCE	DUTY CYCLE	BRAKE TORQUE [Nm]	PROTECTION	THERMAL CLASS
Schindler W53.45.1/2 machine kit	40% ED	2x 60 2x 75 (overexc.)	IP43 DIN40050	F (155°)

Power supply: 48VDC, 80VDC, 180VDC, 230VAC with overexcitation box, ...



W53

SCHINDLER MACHINES' UPDATING



Schindler machines' updating.W53


REFERENCE	DUTY CYCLE	BRAKE TORQUE [Nm]	PROTECTION	THERMAL CLASS
Schindler W53 machine kit	40% ED	2x 70 2x 90 (overexc.)	IP43 DIN40050	F (155°)

Power supply: 48VDC, 80VDC, 180VDC, 230VAC with overexcitation box, ...



W54

SCHINDLER MACHINES' UPDATING




Schindler machines' updating.W54

REFERENCE	DUTY CYCLE	BRAKE TORQUE [Nm]	PROTECTION	THERMAL CLASS
Schindler W54 machine kit	40% ED	2x 135 2x 185 (overexc.)	IP43 DIN40050	F (155°)

Power supply: 48VDC, 80VDC, 180VDC, 230VAC with overexcitation box, ...



W55,W56,W57 SCHINDLER MACHINES' UPDATING



Schindler machines' updating.W55, W56, W57


REFERENCE	DUTY CYCLE	BRAKE TORQUE [Nm]	PROTECTION	THERMAL CLASS	DIMENSIONS		
					A	B	C
Schindler W55 machine kit	40% ED	2x 160 2x 225 (overexc.)	IP43 DIN40050	F (155°)	135	70	155
Schindler W56,W57 machine kit	40% ED	2x 170 2x 245 (overexc.)	IP43 DIN40050	F (155°)	155	95	145

Power supply: 48VDC, 80VDC, 180VDC, 230VAC with overexcitation box, ...



W58,W59

SCHINDLER MACHINES' UPDATING



Schindler machines' updating.W58, W59

REFERENCE	DUTY CYCLE	BRAKE TORQUE [Nm]	PROTECTION	THERMAL CLASS
Schindler W58, W59 machine kit	40% ED	2x 400 2x 475 (overexc.)	IP43 DIN40050	F (155°)

Power supply: 48VDC, 80VDC, 180VDC, 230VAC with overexcitation box, ...

